



## 15 Square Drill Point



## 16 Racon Point

Increased feed rate, increased tool life and reduces burrs.



## 17 Bickford Point

Combination of helical and Racon point features. Self centring ability and reduces burrs. Excellent hole geometry and increased tool life.

